

REPLACEMENT FOR

**LATIN AMERICAN TYPE
RANGER '98**



HEAD LAMP
930.FD2338
R:

**LATIN AMERICAN TYPE
RANGER '05**





HEAD LAMP
930.FD2336
R:

**LATIN AMERICAN TYPE
RANGER '09**



HEAD LAMP
930.FD2335
R:



TAIL LAMP
931.FD1534
R:



TAIL LAMP
931.FD1533
R:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

FD

email:market@daiwa-motor.com