


REPLACEMENT FOR
LIFAN X60



TAIL LAMP
931.LF3003
OE:

TBA



REAR BUMPER REINFORCEMENT
911.LF44006
OE:



HEAD LAMP
930.LF7003
OE:

TBA



FRONT BUMPER
901.LF05005BA
OE:



FRONT BUMPER BRACKET
911.LF44005
OE:



FOG LAMP
939.LF2004
OE:



REAR BUMPER
9
001.LF05006BAE:



REAR BUMPER BRACKET
911.LF44006
OE:



FRONT BUMPER LAMP
932.LF7002
OE:




BUMPER GRILLE
901G.LF06003BA
OE:



MUDGUARD FRONT
922.LF99001Z
OE:



REAR FOG LAMP
939.LF2005
OE:



FRONT BUMPER REINFORCEMENT
911.LF44007A
OE:



INNER FENDER
915.LF010001
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

LIFAN

email:market@daiwa-motor.com