

REPLACEMENT FOR

# ALSVIN '10~on



**BACK LAMP**  
933.CHN5001  
R:



**REAR BUMPER**  
901.CHN05006BA  
OE:



**BUMPER GRILLE**  
901G.CHN01002BA  
OE:




**HEAD LAMP**  
930.CHN2003  
R:



**GRILLE**  
900.CHN08003GA  
OE:



**FRONT BUMPER**  
901.CHN05007BA  
OE:




**FOG LAMP**  
939.CHN3003  
R:




**GRILLE**  
900.CHN08009GA  
OE:



**REAR BUMPER**  
901.CHN05008BA  
OE:




**REAR BUMPER LAMP**  
932.CHN1001  
R:



**GRILLE MOULDING**  
923.CHN01001A  
OE:



**FRONT BUMPER BRACKET**  
911.CHN01003A  
R:




**TAIL LAMP**  
931.CHN4004  
R:



**FRONT BUMPER**  
901.CHN05005BA  
OE:



**REAR BUMPER BRACKET**  
911.CHN01004A  
R:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only. Our production is not original replacement parts but interchangeable against original parts.

**CHNA**

email:market@daiwa-motor.com