

REPLACEMENT FOR

CS.15



TAIL LAMP
931.CHN4006
R:



BUMPER GRILLE
901G.CHN01005BA
OE:




HEAD LAMP
930.CHN2005
R:



GRILLE
900.CHN08005GA
OE:



FOG LAMP COVER
913.CHN1002
R:



FOG LAMP
939.CHN3005
R:



FRONT BUMPER
901.CHN05011BA
OE:



REAR SIDE BUMPER
912.CHN04001
R:



REAR BUMPER LAMP
932.CHN1002
R:



REAR BUMPER
901.CHN05012BA
OE:



BACK LAMP
933.CHN5003
R:



FRONT BUMPER LOWER BOARD
901.CHN05013BA
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

CHNA

email:market@daiwa-motor.com