

REPLACEMENT FOR

TICO



BUMPER LAMP (N/M)
932.DW1614
OE:



TAIL LAMP
931.DW1901
OE:



REAR BUMPER
901.DW04141BA
OE:



HEAD LAMP
930.DW5112
R:35302-78130 L:35301-78130



SIDE LAMP
932.DW1612X
OE:



TAIL LAMP CRYSTAL
931P.DW1901
OE:



REAR BUMPER
901.DW04139BA
OE:



HEAD LAMP W/CLEAR C/L
930.DW5112C
R:35301A78B10-000
L:35101A78B10-000



REAR FOG LAMP
939.DW9015
OE:



MIRROR
980.DW120
OE:



INNER LINER
915.DW11253
OE:



HEAD LAMP CRYSTAL
930P.DW5112
R:35302-78B10 L:35301-78B10



REAR FOG LAMP CRYSTAL
939P.DW9015R
OE:



FRONT BUMPER
901.DW04138BA
OE:71711A-78B00-5PK



BUMPER LAMP
932.DW1613A
OE:



REAR FOG LAMP CRYSTAL
939P.DW9015
OE:



FRONT BUMPER
901.DW04140BA
OE:51210-A78B000-000



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

DW

email:market@daiwa-motor.com