

REPLACEMENT FOR

EXPLORER '11~



FRONT BUMPER VALANCE
903.FD95031VA
OE:BB5Z-17626-BB



BUMPER GRILLE
901G.FD07282GA
OE:BB5Z-17K945-AA



CROSSMEMBER
906.FD21003A
OE:FB5Z-5C145D



GRILLE
900.FD77223GA
OE:BB53-8150-AA



FRONT BUMPER SUPPORT
911.FD44176A
OE:BB5Z-17757-A



FRONT BUMPER BRACKET
911.FD44138
R:BB5Z 17E814A L:BB5Z 17E814B




INNER FENDER FRONT
915.FD11124
R:BB5316A573ADE L:BB5316A574AE



GRILLE
900.FD77224GA
OE:BB53-8A164-AA



REAR BUMPER SUPPORT
911.FD44177A
OE:




TOW COVER
901C.FD11015
OE:BB5Z-17A900-APTM



INNER LINING REAR
915.FD11125
R:BB5Z7828370B L:BB5Z7828371B



FRONT BUMPER UPPER
901.FD05024BA
OE:BB5Z-17D957-BPTM



GRILLE MOULDING LONG
923.FD04006A
OE:BB53-8150-AASMAS



SENSOR HOLE BRACKET
911.FD44182A
R:BB5Z15C872A L:BB5Z15C873A



FENDER TRIM FRONT
943.FD12003
R:BB5Z-16038AA L:BB5Z-16039AA



FRONT BUMPER LOWER
901.FD05025BA
OE:BB5Z-17D957-CBCP



GRILLE MOULDING SHORT
923.FD04007A
OE:BB53-8150-BASMAS



SENSOR HOLE COVER
911.FD44181A
R:BB5Z15C872ABPTM
L:BB5Z15C873ABPTM



FENDER TRIM REAR
943.FD12004
R:BB5Z-7829164AA L:BB5Z-7829165AA

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

FD

email:market@daiwa-motor.com

REPLACEMENT FOR

EXPLORER '11~



WINDSHIELD WASHER
509.FD1012A
OE:



LICENSE BOARD EURO TYPE
942.FD99005A
OE:DB53-14A385-BBV



LICENSE BOARD USA TYPE
942.FD99006A
OE:BB53-17A385-BAW



FOG LAMP BRACKET
911.FD44137
R:BB53-15266-AC L:BB53-15267-AC



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

FD

email:market@daiwa-motor.com