

REPLACEMENT FOR

F150 '15~



HEAD LAMP BRACKET
911.FD44266A
R:FL3417C754C L:FL3417C755C



FOG LAMP COVER
913.FD07014
R:FL3415A254A L:FL3415A255A



FOG LAMP
939.FD7046
R:FL3415201AC L:FL3415201AC



FRONT BUMPER BRACKET
911.FD44268A
OE:FL3Z17B984A



GRILLE
900.FD77239GA
OE:FL348200KB



FRONT BUMPER STRIPE
923.FD04029A
OE:FL3417B968CJW



FRONT BUMPER
901.FD05065BA
OE:FL3417757F



FRONT BUMPER STRIPE
923.FD04028A
OE:FL3417C881AA



FRONT BUMPER BRACKET
911.FD44267A
R:FL34278G06AB L:FL34278B07AB



FRONT BUMPER LOWER
903.FD05081VA
OE:FL3417B635BBW



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

FD

email:market@daiwa-motor.com