


REPLACEMENT FOR
PANDA



TAIL LAMP
931.GEE2001
R:



REAR BUMPER BRACKET
911.GEE44002
R:



HEAD LAMP
930.GEE1002
R:



MIRROR
980.GEE101
R:



INNER FENDER
915.GEE10001
R:



FOG LAMP
939.GEE3001
R:



FRONT BUMPER
901.GEE08005BA
OE:



MUDGUARD
922.GEE1001
OE:



REAR BUMPER LAMP
932.GEE5002
R:



FRONT BUMPER
901.GEE08006BA
OE:



SIDE LAMP
932.GEE5003
OE:



FRONT BUMPER BRACKET
911.GEE44001A
R:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

GE-ELY

email:market@daiwa-motor.com