

REPLACEMENT FOR

CRV '15~



TAIL LAMP UP
931.HD7440 TBA
R:



REAR BUMPER
901.HD05020BA
OE: 71501-T0T-H10



REAR SIDE BUMPER
912.HD41010A
R:71507-TFC-H00 L:71502-TFC-H00




HEAD LAMP ELECTRIC TBA
930.HD7179E
R:33100-TFC-H01 L:33150-TFC-H01



TAIL LAMP
931.HD7439
R:



FRONT BUMPER APRON
901.HD05022BA
OE: 71110-TFA-T00



HEAD LAMP ELECTRIC TBA
930.HD7180E
R:33101-TFC-H11 L:33151-TFC-H11



GRILLE
900.HD08016GA
OE:



REAR BUMPER APRON
901.HD05021BA
OE: 71510-TFA-ZX




FOG LAMP
939.HD7032
R:33900-TFC-H01 L:33950-TFC-H01



FRONT BUMPER
901.HD05019BA
OE: 71101-TFC-H00



BUMPER GRILLE
901G.HD04973BA
OE: 71180-TFA-H10



REAR BUMPER LAMP
932.HD7005
OE:



FRONT BUMPER DOWN
901.HD05018BA
OE: 71102-TFC-H00



COVER, ENGINE UNDER
957.HD22013A
OE: 74111-TFA-Z00



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HD

email:market@daiwa-motor.com