

REPLACEMENT FOR

ODYSSEY '09



TAIL LAMP
931.HD7446
R:33501-SLG-H01 L:33551-SLG-H01




FRONT BUMPER VALANCE
903.HD05021A
OE:71108-SLG-H00



REAR BUMPER BRACKET
911.HD44788A
R:71593-SLG-H00 L:71598-SLG-H00



HEAD LAMP
930.HD7110E
R:33101-SLG-H01 L:33151-SLG-H01



BACK LAMP
933.HD7005
R:33150-SLG-H01 L:33155-SLG-H01



BUMPER GRILLE
901G.HD07184BA
OE:71103-SLE-901



HEAD LAMP BRACKET
911.HD44733
R:71140-SLE-000 L:71190-SLE-000



HEAD LAMP XENON
930.HD7111E
R:



GRILLE
900.HD08023GA
OE:71121-SNA-A50



FRONT BUMPER REINFORCEMENT
911.HD44785A
OE:71130-SLE-000



TOP COVER RADIATOR
911.HD44784A
OE:71123-SLG-W00



FOG LAMP
939.HD6012
R:33900-SLG-H01 L:33950-SLG-H01



FRONT BUMPER
901.HD05040BA
OE:71101-SLG-H01



REAR BUMPER REINFORCEMENT
911.HD44786A
OE:71530-SFJ-W00ZZ



INNER FENDER
915.HD11203
R:74101-SFE-000 L:74151-SFE-000



REAR BUMPER LAMP
932.HD7014
R:33505-SLG-H01 L:33555-SLG-H01



FRONT BUMPER MLDG
923.HD55161A
OE:71102-SLG-H01



FRONT BUMPER BRACKET
911.HD44734
R:71193-SLE-000 L:71198-SLE-000



REAR TOW COVER
901C.HD11005A
OE:71504-SLE-000




All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HD

email:market@daiwa-motor.com

REPLACEMENT FOR




ODYSSEY '09



WINDSHIELD WASHER
509.HD6192
OE:76841-SLG-S01



SPARE TANK
509.HD6193
OE:19101-RLF-000



LICENSE PLATE BOARD
942.HD2505A
OE:74890-SLG-H01



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HD

email:market@daiwa-motor.com