

REPLACEMENT FOR


ATOS '98~



TAIL LAMP
931.HY1920
R 92402-05100 L 92401-05100



GRILLE
900.HY07929GA
OE:86360-02000



FRONT BUMPER MESHWORK COVER
901G.HY04010BA
OE:86512-02000



HEAD LAMP
930.HY6199
R 92101-02010 L 92102-02010



TAIL LAMP
931.HY1907
R 92402-02010 L 92401-02010



FRONT BUMPER
901.HY042119
OE:86511-02000



FRONT REINFORCEMENT
911.HY44025A
OE:86530-02000



FOG LAMP
939.HY2002
R 92202-02100 L 92201-02100



GRILLE CHROME
900.HY072125CA
OE:86361-02100



FRONT BUMPER
901.HY04222BA
OE:86511-02020



REAR REINFORCEMENT
911.HY44026A
OE:86630-02000



FOG LAMP
939.HY2002A
R 92202-02000 L 92201-02000



GRILLE BLACK
900.HY072125BA
OE:86361-02000



REAR BUMPER
901.HY04223BA
OE:86611-02020



CROSSMEMBER
906.HY21101A
OE:62401-02000



FOG LAMP
939.HY2012
OE:



GRILLE
900.HY07925GA
OE:



REAR BUMPER
901.HY04224BA
OE:86611-02001BU



CROSSMEMBER
906.HY21102A
OE:55100-02000

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only. Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com