

REPLACEMENT FOR

HD 65



TAIL LAMP
931.HY9694
R 92420-4F030 L 92410-4F030

REPLACEMENT FOR


HD 75



FRONT BUMPER
901.HY07026BA
OE:



HEAD LAMP
930.HY9126
R 92120-4F030 L 92110-4F030



HEAD LAMP
930.HY7012
OE:



MIRROR
980.HY147
R:




CORNER LAMP
938.HY9001
R 92320-4F030 L 92310-4F030





CORNER LAMP
938.HY7001
R:




MIRROR HEAD
980.HY148
OE:



SIDE LAMP
932.HY998X
OE:



FOG LAMP
939.HY7209
OE:



FOG LAMP
939.HY9133
R 92220-4F030 L 92210-4F030



TAIL LAMP
931.HY9694
R 92420-4F030 L 92410-4F030



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com