

REPLACEMENT FOR
i10 '18



TAIL LAMP
931.HY7028
R:92402-B4700 L:92401-B4700



FRONT BUMPER GRILLE
901G.HY04132BA
OE:86560-B4810



REAR INNER FENDER
915.HY11140
R:86816-B4000 L:86815-B4000




FOG LAMP
939.HY2030
R:92202-B4600 L:92201-B4600



GRILLE
900.HY08017GA
OE:86350-B4800



REAR BUMPER GRILLE
901G.HY04133BA
OE:86683-B4700



FOG LAMP LED
939.HY2031
R:92202-B4700 L:92201-B4700



FRONT BUMPER
901.HY05028BA
OE:86511-B4800



FRONT BUMPER BRACKET
911.HY44381A
R:86514/6-B4500 L:86513/5-B4500



REAR BUMPER LAMP
932.HY7032
R:92406-B4700 L:92405-B4700



REAR BUMPER
901.HY05029BA
OE:86611-B4710



REAR BUMPER BRACKET
911.HY44382A
R:86616-B4700 L:86615-B4700



BACK LAMP
933.HY7320
R:92404-B4700 L:92403-B4700



FRONT BUMPER GRILLE
901G.HY04131BA
OE:86560-B4800



FRONT INNER FENDER
915.HY11139
R:86814-B4000 L:86813-B4000



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com