

REPLACEMENT FOR
KB 26 89~

REPLACEMENT FOR
**SL-TFR
KB140'97**



LIGHT LAMP
913.IZ1712
OE:



FRONT LAMP
932.IZ1624A
R:



HEAD LAMP
930.IZ7398
R 8-94434557-0 L 8-94434558-0



SIDE LAMP
937.IZ7330
R 8-94225216-0 L 8-9422521X7-0



FRONT LAMP
932.IZ1624CL
OE:



CORNER LAMP
938.IZ3178
R 8-94324-104 L 8-94324-105



FRONT LAMP
932.IZ1619
R 8-97173535-0 L 8-97173536-0




HEAD LAMP
930.IZ1116
R 8-97162177-0 L 8-97162178-0




TAIL LAMP
931.IZ3383
R 8-97910303-0 L 8-97910304-0



CORNER LAMP
938.IZ3178AZ
R 8-94434-569 L 8-94434-57-0



HEAD LAMP
930.IZ1123
R 8-97213005-0 L 8-97213006-0



FRONT LAMP
932.IZ7254
R 8-94434567-2 L 8-94434575-2



CORNER LAMP
938.IZ1523
R 8-979111954-0 L 8-97111855-0



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.