

REPLACEMENT FOR

PICANTO '16~



TAIL LAMP LED
931.KA7221
R:92402-1Y300 L:92401-1Y300



FRONT BUMPER LOWER
901.KA05042BA
OE:86590-1Y300



REAR BUMPER REINFORCEMENT
911.KA44759A
OE:



HEAD LAMP
930.KA7019
R:92102-1Y500 L:92101-1Y500



GRILLE
900.KA07110GA
OE:86350-1Y500



FOG LAMP COVER
913.KA1218
R:86528-1Y500 L:86527-1Y500



REAR BUMPER BRACKET SIDE
911.KA44756
R:



FOG LAMP
939.KA7035
R:92202-1Y500 L:92201-1Y500



FRONT BUMPER
901.KA05039BA
OE: 86511-1Y500



FOG LAMP COVER
913.KA1219
R:86548-1Y520 L:86547-1Y520



REAR BUMPER BRACKET SIDE
911.KA44757
R:86686-1Y310 L:86685-1Y310



FOG LAMP
939.KA7036
R:



REAR BUMPER
901.KA05040BA
OE: 86611-1Y700



BUMPER GRILLE
901G.KA04318BA
OE: 86560-1Y500




RADIATOR SUPPORT
904.KA33033A
OE: 64101-1Y600



REAR BUMPER LAMP
932.KA7011
R:92462-1Y500 L:92461-1Y500



FRONT BUMPER LOWER
901.KA05041BA
OE: 86612-1Y700



FRONT BUMPER REINFORCEMENT
911.KA44758A
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

KA

email:market@daiwa-motor.com