

REPLACEMENT FOR

LIFAN 320



TAIL LAMP
931.LF3001
R:F4133300B1 L:F4133400B1



FRONT BUMPER BRACKET
911.LF44001
OE:



INNER FENDER REAR TBA
9
OE:



HEAD LAMP
930.LF7001
OE:




MIRROR ELECTRIC
980.LF1001E
OE:



REAR BUMPER BRACKET
911.LF44002
OE:



AIR FILTER CASE TBA
OE:



FOG LAMP
939.LF2001
OE:



GRILLE
900.LF04001GA
OE:



MUDGUARD FRONT TBA
922.LF99003Z
OE:



SIDE LAMP
932.LF7001X
OE:



FRONT BUMPER
901.LF05001BA
OE:



MUDGUARD REAR TBA
922.LF99004Z
OE:



REAR FOG LAMP
939.LF2002
OE:



REAR BUMPER
901.LF05002BA
OE:



INNER FENDER FRONT TBA
915.LF010002
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

LIFAN

email:market@daiwa-motor.com