

REPLACEMENT FOR
LIFAN 620



GRILLE
900.LF04002GA
OE:




FRONT BUMPER BRACKET TBA
911.LF44003
OE:



HEAD LAMP
930.LF7002
OE:



FRONT BUMPER
901.LF05003BA
OE:



REAR BUMPER BRACKET TBA
911.LF44004
OE:



FOG LAMP
939.LF2003
OE:



REAR BUMPER
901.LF05004BA
OE:



TAIL LAMP
931.LF3002
OE:



BUMPER GRILLE
901G.LF06001BA
OE:



MIRROR TBA
980.LF1002
OE:



BUMPER GRILLE SIDE
901G.LF06002BA
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

LIFAN

email:market@daiwa-motor.com