

REPLACEMENT FOR

L200 PUP 87~ COLT 94~



TAIL LAMP
931.MB1546K
R MB527102

L MB527101

REPLACEMENT FOR

L200 95~



TAIL LAMP
931.MB3073C
R:MR109128

L:MR109127



CORNER LAMP
938.MB1362C
R Mb527092

L MB527091



HEAD LAMP
930.MBA297

R: MB 439534

L:MB 439533



FRONT LAMP
932.MB1549
OE:



CORNER LAMP
938.MB1362K
R:MB527090

L:MB527089




SIDE LAMP
932.MB1405
R:




SIDE LAMP
932.MB1308
R:MB527080

L:MB527079



SIDE LAMP
932.MB3277X
OE: MB847540



TAIL LAMP
931.MB1546C
R MB827104

L MB527103



TAIL LAMP
931.MB3073
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

MS

email:market@daiwa-motor.com