

REPLACEMENT FOR

T3000/T3500 /T4100'89-'ON



CORNER LAMP
938.MZ3100
OE:

REPLACEMENT FOR

PICK UP B2000/2200



TAIL LAMP
931.MZ1505Y
OE:



HEAD LAMP
930.MZ3058
OE:



TAIL LAMP
931.MZ3071
OE:



CORNER LAMP
938.MZ1326
R UB8551090 L UB855100



TAIL LAMP
931.MZ1505C
R 8BU251150 L 8BU251160




CORNER LAMP
938.MZ7084
OE:




CORNER LAMP
938.MZ1328A
R UB7551090A L BU755100A



CORNER LAMP
938.MZ7085
OE:



SIDE LAMP
932.MZ1243
R UB3951060 L UB3951070



CORNER LAMP
938.MZ3099
OE:



TAIL LAMP
931.MZ1505K
R 8BU151150 L 8BU151160



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

MZ

email:market@daiwa-motor.com