

REPLACEMENT FOR
PATHFINDER

REPLACEMENT FOR
PATROL
02~

REPLACEMENT FOR
PATROL
04~



HEAD LAMP 98-
930.NS1136 315-1136-US
R 26010-2W625 L 26060-2W625



CORNER LAMP CHROME
938.NS1144C 215-1559-1
R B6170-60G00 L B6175-60G00



HEAD LAMP 05-
930.NS1159 315-1159
OE:



CORNER LAMP BLACK
938.NS1144K 215-1559-2
R B6170-43G02 L B6175-43G02



HEAD LAMP
930.NS7007 215-1192
R 26010-VC3 25 L 26060-VC325



HEAD LAMP ELECTRIC
930.NS11A2 215-11A2
R 26010-VD325 L 26060-VD325





WATER TANK '01~'04
509.NS1123
OE:21710-2W101




CORNER LAMP BLACK
938.NS1563 215-1563
R B6110-41G00 L B6115-41G00



CORNER LAMP
938.NS1595 215-1595
R 26110-VC325 L 26115-VC325



TAIL LAMP
931.NS19F8
R 26550-VC327 L 26555-VC327



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

NS

email:market@daiwa-motor.com