

REPLACEMENT FOR
B12 '89~

REPLACEMENT FOR
B13 '92~

REPLACEMENT FOR
B13 '00~



TAIL LAMP
931.NS1993 215-1991-3A-CR
OE:



HEAD LAMP
930.NS1306 215-1111
R:26010-60A00 L:26060-60A00



HEAD LAMP
930.NS7682 215-1154
R:26015-87Y00 L:26060-87Y00



HEAD LAMP
930.NS1142 315-1142-US
OE:



TAIL LAMP
931.NS1992 215-1991-4A-CR
R 26550-F4215 L 26550-F4215




CORNER LAMP
938.NS1415 215-1519Y
R B1670-70A00 L:B1675-70A00



CORNER LAMP
938.NS3305 215-1562
R:B6120-85Y00 L:B6125-85Y00




HEAD LAMP
930.NS1143 315-1142-USN
R 26120-F4202 L 26125-F4202




GRILLE
900.NS07262GA
OE:



CORNER LAMP
938.NS1415C 215-1519C
OE:



CORNER LAMP
938.NS1562 215-1562-A-CU
R 26120-F4202 L 26125-F4202



TAIL LAMP
931.NS1498 215-1591-A-CR
R 26550-52A00 L:26555-52A00



TAIL LAMP
931.NS1991 215-1591-A-CR
R 26550-F4202 L 26555-F4202



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

NS

email:market@daiwa-motor.com