

REPLACEMENT FOR

TEANA 04~on



TAIL LAMP
931.NS0002 115-1924
R:26550-YJ000 L:26555-YJ000



RADIATOR SUPPORT
904.NS30936A
OE:62500-9W200



INNER FENDER
915.NS11098
R:63844-9W200 L:63845-9W200



MIRROR
980.NS994E
OE:



FRONT BUMPER SUPPORT
911.NS44223
R:62220-9Y000 L:62221-9Y000



HEAD LAMP
930.NS1114
R:26010-2DR0A L:26060-2DR0A



FRONT BUMPER
901.NS04992BA
OE:62022-9W240



SIDE SKIRT
908.NS2003A
R:70850-9W200 L:70851-9W200



FOG LAMP
939.NS2008
R:26150-89929 L:26155-89929



REAR BUMPER
901.NS04993BA
OE:85022-9W240



FRONT MUDGUARD
922.NS6005Z
OE:F38E09W2D0



TAIL LAMP
931.NS0003 1115-1920
R:26550-9W200 L:26555-9W200



GRILLE
900.NS07283GA
OE:62310-9W000



REAR MUDGUARD
922.NS6006Z
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

NS

email:market@daiwa-motor.com