

REPLACEMENT FOR

OCTAVIA '96~'03



SIDE LAMP
932.SK7002
OE



INNER FENDER
915.SK11006
R:1U0809962D L:1U0809961C



HEAD LAMP
930.SK6231
R:1U1941018 L:1U1941017



SIDE LAMP
932.SK7001
OE



RADIATOR SUPPORT
904.SK10006A
OE:6Y0805588K



CORNER LAMP
938.SKA207
R:1U0953156D L:1U0953155D



MIRROR
980.SK1006E
R:



RADIATOR SUPPORT
904.SK10005A
OE:6Y0805588L



FOG LAMP
939.SK7405
R:6Y0941700A L:6Y0941699A



GRILLE
901.SK
OE: 1U0853651



TAIL LAMP
931.SKA385
R:1U6945095C L:1U6945096C



FOG LAMP COVER
913.SK7210
R:1U0807638B L:1U0807367B



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

SK

email:market@daiwa-motor.com