

REPLACEMENT FOR

RAPID '13



FRONT BUMPER
901.SK05004BA
OE:



BUMPER BRACKET
911.SK44032A
R:32D805932 L:32D805931



BUMPER GRILLE
901G.SK04710BA
OE:32D853677



HEAD LAMP
930.SK7004E
R:5JF941018 L:5JF941017



FRONT BUMPER
901.SK05003BA
OE:5JA807221



FRONT BUMPER BRACKET
911.SK44028A
R:32D807050 L:32D807049




FOG LAMP COVER
913.SK7206
R:5JA80768 L:5JA807682



FOG LAMP
939.SK7406
R:32D941700 L:32D941699



FRONT BUMPER APRON
903.SK05006VA
OE:



RADIATOR PANEL
911.SK44031A
R:32D121284A L:32D121283A



FOG LAMP COVER
913.SK7213
R:5JA807368 L:5JA807367



TAIL LAMP
931.SK7106
R:32D945096 L:32D945095



FRONT BUMPER REINFORCEMENT
911.SK44033A
OE:



REAR BUMPER BRACKET
911.SK44029A
R:34D807394B L:34D807393B



ENGINE UNDER COVER
957.SK22009A
OE:



GRILLE
900.SK08004GA
OE:5JA853668



FRONT BUMPER BRACKET
911.SK44030A
OE:34D807863A



RADIATOR SUPPORT
904.SK10010A
OE:34D805588



MUDGUARD
922.SK12004Z
OE:

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

SK

email:market@daiwa-motor.com