

REPLACEMENT FOR

CARINA ST212



REPLACEMENT FOR

CHASER '96~



TAIL LAMP
931.TY7022
OE:




HEAD LAMP
930.TY7012
R 81130-2B720 L 81170-2B680



HEAD LAMP
930.TY7903
OE:



TAIL LAMP
931.TY7023
OE:



CORNER LAMP CARINA'98
938.TY7010
R 81511-20820 L 81521-20810





CORNER LAMP
938.TY7013C
R 81511-22430 L 81521-22430



TAIL LAMP
931.TY7027
OE:



CORNER LAMP
938.TY7013A
R 81511-22440 L 81521-22440



CORNER LAMP
938.TY7014
R 81731-22130 L 81741-22130



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

TY

email:market@daiwa-motor.com