

REPLACEMENT FOR

COROLLA AE100

'92~on



CORNER LAMP (EURO TYPE)
938.TY5047 212-1575
R 81610-12580 L 81620-12580



TAIL LAMP
931.TY1800 212-1967-A
R 81550-1A720 L 81560-1A630



HEAD LAMP CRYSTAL
930P.TY1826
OE:



FRONT LAMP
932.TY1415A 212-1654
R 81510-12670 L 81520-12580



TAIL LAMP
931.TY1863 212-1979PXA
OE:



CORNER LAMP CRYSTAL
938P.TY1889
OE:



HEAD LAMP
930.TY1826 212-1142
R 81110-1E280A L 81150-1E550A



FRONT LAMP
932.TY1495 212-1661-AE
R 81510-12770 L 81520-12750



TAIL LAMP
931.TY3041 212-1991
R 81551-13350 L 81561-13350



GARNISH
941P.TY1097
OE:




HEAD LAMP
930.TY1744 312-1104
R 81110-1E221 L 81150-1A491



FRONT LAMP
932.TY1417C 212-1661P-C
OE:



TAIL LAMP
931.TY1990 212-1990
R 81551-1A751 L 81561-1A691



CORNER LAMP
936.TY1889 212-1561
R 81610-12530 L 81620-12530



SIGNAL LAMP H/B
932.TY1679 212-1665
R 81510-12740 L 81520-12740



GRILLE
900.TY07134GA
OE:53101-12860



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

TY

email:market@daiwa-motor.com