

REPLACEMENT FOR

HIACE YH/LH '84~



CORNER LAMP
938.TY1616 212-1626-A
R 81551-95J07 L 81561-95J07



F/SIDE BUMPER
912.TY41099F
R 52112-29035 L 52113-29035



REAR BUMPER(WITH HOLE)
901.TY04972BA
OE:



CORNER LAMP
938.TY1527
R 81610-29345 L 81620-29335



CORNER LAMP
938.TY7026 212-1626-A
OE:



R/SIDE BUMPER
912.TY41099
R 52165-29015 L 52166-29015



REAR BUMPER(WITHOUT HOLE)
OE:



CORNER LAMP
938.TY1528C 212-1528-CA
R 81610-95J01 L 81620-95J01



TAIL LAMP
931.TY7018 212-1939
R 81551-95J07 L 81561-95J07



PANEL UNIT
OE:



INNER BRACKET REAR BUMPER
OE:



CORNER LAMP
938.TY1425 212-1527-A
OE:



TAIL LAMP
931.TY1387 212-1916
R 81550-80153 L 81560-80158



FRONT BUMPER WITH FOG LAMP
901.TY04970BA
OE:



UPRIGHT POST
OE:



CORNER LAMP
938.TY1528A 212-1528-YA
R 81510-95J03 L 81510-95J03



LIGHT LAMP
913.TY074043HA
R 53130-29155 L 53140-29155



FRONT BUMPER WITHOUT HOLE
901.TY04971BA
OE:



SUPPORT OF FRONT BUMPER
OE:

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

TY

email:market@daiwa-motor.com