

REPLACEMENT FOR  
**IPSUM**  
'96~



REPLACEMENT FOR  
**IPSUM**  
'98~



REPLACEMENT FOR  
**IPSUM**  
'01~



**FRONT BUMPER**  
901.TY05019BA  
OE:



**HEAD LAMP**  
930.TY7902  
OE:



**HEAD LAMP**  
930.TY7905  
OE:



**HEAD LAMP**  
930.TY7757  
OE:



**CORNER LAMP**  
938.TY7012  
R 81511-44010 L 81512-44010



**CORNER LAMP**  
938.TY7017  
OE:



**FOG LAMP**  
939.TY7017  
OE:



**FOG LAMP**  
939.TY7016  
OE:



**TAIL LAMP**  
931.TY7035  
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.  
Our production is not original replacement parts but interchangeable against original parts.

**TY**

email:market@daiwa-motor.com