

REPLACEMENT FOR
NADIA
SXN10 '98



REPLACEMENT FOR
NOAH
'96~on



FRONT BUMPER
901.TY05120BA
OE:



HEAD LAMP
930.TY7021
OE:



HEAD LAMP
930.TY7754
OE:



HEAD LAMP
930.TY7906
OE:



CORNER LAMP
938.TY7023
OE:



HEAD LAMP
930.TY7022
OE:



CORNER LAMP
938.TY7028
OE:



CORNER LAMP
938.TY7018
OE:



LIGHT CASE
930K.TY1002
OE:53132-28061



TAIL LAMP
931.TY7034
OE:



CORNER LAMP
938.TY7019
OE:



GRILLE
900.TY08009GA
OE:53100-28120



FRONT BUMPER
901.TY05018BA
OE:52119-44110



FOG LAMP
939.TY7001
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

TY

email:market@daiwa-motor.com