

REPLACEMENT FOR
MARK II



REPLACEMENT FOR
REIZ



REPLACEMENT FOR
RUSH '10~



FRONT BUMPER
901.TY40904BA
OE:52119-0P010



HEAD LAMP
930.TY7037
OE:



HEAD LAMP
930.TY7007
OE:



REAR BUMPER
901.TY40905BA
OE:52159-0P010



HEAD LAMP
930.TY11M6
OE: 212-11M6



TAIL LAMP
931.TY7058
OE:



SIDE LAMP
932.TY7037X
OE:



GRILLE LAMP
900.TY7983GA
OE:53111-0P010



TAIL LAMP
931.TY19W1
OE: 212-19W1



TAIL LAMP
931P.TY7058
OE:



TAIL LAMP
931.TY7019
OE:



HOOD MOULDING
923.TY2508A
OE:53381-0P010-C



TAIL LAMP
931.TY7059
OE:



TAIL LAMP
931.TY7060
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

TY

email:market@daiwa-motor.com