

REPLACEMENT FOR

TEANA '08



FRONT BUMPER
901.NS07930BA(w/ WASHER HOLE)
901.NS07930BB(w/o WASHER HOLE)
OE:62022-JN00H




COVER, ENGINE UNDER
957.NS22015A
OE:75892-JN00A



HEAD LAMP
930.NS1122E
R:26025-JN90A L:26075-JN90A



REAR BUMPER
901.NS07931BA
OE:85022-JN00H



WATER TANK SIDE PANEL
911.NS44963
R:92184-JN00A L:92185-JN00A



HEAD LAMP XENON TYPE
930.NS1122E-1
R:



INNER FENDER
915.NS11097
R:63840-JN00A L:63841-JN00A




SIDE SKIRT
908.NS52006A
R:76850-JN90A L:76851-JN20A



TAIL LAMP
931.NSB229
R:26550-JN00A-A124
L:26555-JN00A-A124



FRONT BUMPER MOULDING
923.NS2010
R:62074-JN00A L:62075-JN00A



FAN SHROUD
512.NS2016
OE:62500-JN00A



GRILLE
900.NS27289GA
OE:62310-JN03A-A091



REAR BUMPER MOULDING
923.NS2011
R:65074-JN00A L:65075-JN00A



MIRROR ELECTRIC, FOLDABLE
980.NS271E-1
980.NS271E-2 W/HEATER
R:96301-JN00A L:96302-JN00A



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

NS

email:market@daiwa-motor.com