

REPLACEMENT FOR

SANTA FE '19



DAYTIME RUNNING LAMP
971.HY0103
R:92208-S1000 L:92207-S1000



TAIL LAMP LED
931.HY7030
R:92402-S1100 L:92401-S1100



REAR BUMPER LOWER
901.HY05040BA
OE:86650-S1000 / 86612-S1000



HEAD LAMP
930.HY7151
R:92102-S1000 L:92101-S1000



DAYTIME RUNNING LAMP
971.HY0104
R:92208-S2000 L:92207-S2000



GRILLE
900.HY08021GA
OE:86350-S1110 / S1000



FRONT BUMPER GRILLE
901G.HY04134BA
OE:86531-S1000



HEAD LAMP
930.HY7152
R:92102-S1100 L:92101-S1100



BACK LAMP
933.HY7323
R:92404-S1000 L:92403-S1000



FRONT BUMPER UPPER
901.HY05037BA
OE:86510-S1000 / 86511-S1000



FRONT BUMPER GRILLE
901G.HY04135BA
OE:86531-S1010



FOG LAMP
939.HY2032
R:92202-S1100 L:92201-S1100



BACK LAMP LED
933.HY7324
R:92404-S1100 L:92403-S1100



FRONT BUMPER LOWER
901.HY05038BA
OE:86512-S1000



BUMPER GRILLE SIDE
901G.HY04136BA
R:86596-S1000 L:86595-S1000



REAR FOG LAMP
932.HY7034
R:



TAIL LAMP
931.HY7029
R:92402-S1000 L:92401-S1000



REAR BUMPER
901.HY05039BA
OE:86611-S1000



FRONT BUMPER REINFORCEMENT
911.HY44389A
OE:64900-S1020

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com

REPLACEMENT FOR

SANTA FE '19



FRONT BUMPER BRACKET
911.HY44392A
R:86552-S1000 L:86551-S1000



GRILLE MOULDING
923.HY55873A
OE:86374-S1000



REAR INNER FENDER
915.HY11155
R:86822-S1000 L:86821-S1000



FRONT BUMPER REINFORCEMENT
911.HY44390A
OE:64900-S1030



FRONT BUMPER BRACKET
911.HY44393A
R:86556-S1000 L:86555-S1000



REAR BUMPER MOULDING
923.HY55874A
R:86692-S1010 L:86691-S1010



WATER TANK UPPER BOARD
911.HY44395
OE:86390-S1000



REAR BUMPER REINFORCEMENT
911.HY44391A
OE:86631-S1000



REAR BUMPER BRACKET
911.HY44394A
R:86652/54-S1000 L:86651/53-S1000



REAR BUMPER MOULDING
923.HY55875A
OE:86699-S1000



RADIATOR SUPPORT
904.HY30354A
OE:64101-S1000



FRONT BUMPER BOARD
957.HY22027A
OE:86577-S1000



GRILLE MOULDING
923.HY55871A
OE:86374-S1010




FENDER TRIM
943.HY12002
R:87712-S1000CA L:87711-S1000CA



LICENSE PLATE BOARD
942.HY2505A
OE:86519-S1000



SKID PLATE REAR BUMPER
910.HY14005A
OE:86670-S1000 / 86671-S1000



GRILLE MOULDING
923.HY55872A
R:86376-S1030/S1010
L:86375-S1030/S1010



FRONT INNER FENDER
915.HY11154
R:86812-S1000 L:86811-S1000



AIR DUCT FRONT BUMPER
911.HY44396A
R:86542-S1000 L:86541-S1000





All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com

REPLACEMENT FOR





SANTA FE '19



TOW COVER
901C.HY0002
OE:86517-S1000



FOG LAMP COVER
913.HY07045
R:86564-S1000 L:86563-S1000



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com