

REPLACEMENT FOR

FORTUNER '16



REAR FOG LAMP LED
939.TY7211

R:



BUMPER GRILLE
901G.TY05061BA

OE:



MUDGUARD
922.TY20876A

OE:



HEAD LAMP MANUAL TYPE
930.TY3010

R:



3RD BRAKE LAMP

940.TY1009A

OE:



FRONT BUMPER BRACKET TBA

911.TY44209A

R:



FAN SHROUD DIESEL

512.TY2032

OE:



TAIL LAMP
931.TY6365

R:



GRILLE
900.TY08097GA

OE



REAR BUMPER BRACKET TBA

911.TY44210

R:



FAN SHROUD PETROL

512.TY2036

OE



BACK LAMP
933.TY1331

R:



FRONT BUMPER

901.TY05022BA


OE:



FOG LAMP COVER

913.TY07944A

OE:



REAR FOG LAMP
939.TY7210

R:



REAR BUMPER
901.TY05023BA

OE:



TAIL GATE CHROME STRIPE
923.TY55173A

OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only. Our production is not original replacement parts but interchangeable against original parts.

TY

email:market@daiwa-motor.com