

REPLACEMENT FOR

# 100 '83~'90



**TAIL LAMP**  
931.AD1914  
R 443945218 L 443945217



**INNER FENDER**  
915.AD11099  
R 443821111B L 443821111C




**BUMPER GRILLE**  
901G.AD11011GA  
OE:443853667



**HEAD LAMP**  
930.AD5009  
R 443941030E L 443941029E




**REAR BUMPER**  
901.AD04130BA  
OE:443807301



**FOG LAMP FRAME**  
919.AD1134  
R 443807163 L 443807164



**MIRROR ELECTRIC W/HEATER**  
980.AD003T  
R:



**CORNER LAMP**  
938.AD1910C  
OE:



**FRONT BUMPER**  
901.AD04003BB  
OE:443801101C



**FAN SHROUD**  
515.AD1138  
OE:443121207



**CORNER LAMP**  
938.AD1910  
R 443953050E L 443953049E



**BACK LAMP**  
933.AD1301  
R 443945226 L 443945225



**H/LAMP MOULDING**  
923.AD55127Z  
R 443805617 L 443805618



**FOG LAMP**  
939.AD2002  
OE:443941699E



**INNER DOOR HANDLE**  
881.AD1136Z  
R 443837020 L 443839019



**FOG LAMP**  
939.AD7002R/L  
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only. Our production is not original replacement parts but interchangeable against original parts.

## AD

email:market@daiwa-motor.com