

REPLACEMENT FOR


A6 '94~'97



TAIL LAMP
931.AD1924
R:4A5954218B L:4A5954218B




SUPPORT '95~'97 1.8
904.AD30186A
OE:4B0805588A




HEAD LAMP
930.AD5003
R:1EL007270-151 L:1EL007270-161



MIRROR
980.AD703E
R:4A1858532 L:4A1858531




SUPPORT '95~'97 2.4
904.AD30185A
OE:4B0805588G



CORNER LAMP
938.AD5265C
R:4A0953050D L:4A0953049D




FRONT BUMPER
901.AD04995BA
OE:4A0807103DA



CORNER LAMP
938.AD5265A
R:4A0953050 L:4A0953049




BUMPER GRILLE
901G.AD99009BA
OE:4A0807683A



BACK LAMP
933.AD7001
R:4A0945223D L:4A0945224D



BUMPER GRILLE SIDE
901G.AD99008GA
R:4A0807346J L:4A0807345J



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only. Our production is not original replacement parts but interchangeable against original parts.

AD

email:market@daiwa-motor.com