


REPLACEMENT FOR


A8 '12



FRONT BUMPER REINFORCEMENT
911.AD44051A
OE:4H0807109B



REAR BUMPER MOULDING
923.AD55195A
OE:4H0807443




SIDE SKIRT
908.AD33002
R:



HEAD LAMP
930.AD7011E
R:



REAR BUMPER BRACKET
911.AD44052A
OE:4H0807309C



FOG LAMP COVER
913.AD11022A
R:4H0807680D L:4H0807679D



TOW COVER
901C.AD11013A
OE:4H0807241GRU



FRONT BUMPER
901.AD05015BA
OE:4H0807066C



RADIATOR SUPPORT
904.AD30202A
OE:4H0805594E



FOG LAMP COVER
913.AD11023A
R:4H0807680L L:4H0807679L



WASHER COVER
901C.AD11012A
R:4H0955270GRU L:4H0955269GRU



REAR BUMPER
901.AD05016BA
OE:4H0807067



COVER, UNDER ENGINE
957.AD11012A
OE:4H0825235H



FOG LAMP COVER
913.AD11024A
R:4H0807680E L:4H0807679E



WATER POT
509.AD1009
OE:4E0955453J



REAR BUMPER VALANCE
903.AD06106VA
OE:4H0807521



FRONT BUMPER BRACKET
911.AD44050A
R:4H0807284 L:4H0807283



FOG LAMP COVER
913.AD11025A
R:4H0807680M L:4H0807679M

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only. Our production is not original replacement parts but interchangeable against original parts.

AD

email:market@daiwa-motor.com