

REPLACEMENT FOR

X5 E53 '02~'04



SIDE LAMP
933.BM1404A
OE:



TAIL LAMP
931.BM
OE:



HEAD LAMP
930.BM1148
R



SIDE LAMP
932.BM1404C
OE:



BACK LAMP
933.BM
OE:



HEAD LAMP
930P.BM1152
OE:



FOG LAMP
939.BM2004
OE:



GRILLE
900.BM07908GA
OE:



HEAD LAMP
930.BM1152
OE:



FOG LAMP
939.BM5717
OE:



GRILLE
900.BM07908GB
OE:



HEAD LAMP
930.BMA607
R



TAIL LAMP
931.BM1928
OE:



DOOR MOULDING
923.BM99054A
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only. Our production is not original replacement parts but interchangeable against original parts.

BM

email:market@daiwa-motor.com