

REPLACEMENT FOR

F0



MIRROR ELECTRIC
980.BYD1001E
R:



FOG LAMP RIM
913.BYD0101
OE:




WATER POT
509.BYD1001A
OE:




HEAD LAMP
930.BYD1001
OE:



GRILLE
900.BYD08001GA
OE:



FRONT BUMPER MOULDING
923.BYD04001A
OE:



HEAD LAMP
930.BYD1003
OE:



FRONT BUMPER
901.BYD05001BA
OE:



REAR BUMPER MOULDING
923.BYD04002A
OE:





FOG LAMP
939.BYD4001
OE:



REAR BUMPER
901.BYD05002BA
OE:



INNER FENDER
915.BYD11001A
OE:



TAIL LAMP
931.BYD3001
OE:



BUMPER GRILLE
901G.BYD01010BA
OE:



MUDGUARD
922.BYD5001Z
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only. Our production is not original replacement parts but interchangeable against original parts.

BYD

email:market@daiwa-motor.com