

REPLACEMENT FOR

EADO '12~'13



BACK LAMP
933.CHN5005
R:



BUMPER GRILLE
901G.CHN01007BA
OE:



INNER FENDER
915.CHN11005A
R:



HEAD LAMP
930.CHN2008
R:



MIRROR
980.CHN1006E
980.CHN1007E
R:



FRONT BUMPER REINFORCEMENT
911.CHN01016A
OE:



WATER TANK TOP PANEL
911.CHN01015A
OE:



FOG LAMP
939.CHN3007
R:



GRILLE
900.CHN08008GA
OE:



REAR BUMPER REINFORCEMENT
911.CHN01017A
OE:




REAR BUMPER LAMP
932.CHN1005
R:



FRONT BUMPER
901.CHN05018BA
OE:



FRONT BUMPER BRACKET
911.CHN01013A
R:



TAIL LAMP
931.CHN4008
R:



REAR BUMPER
901.CHN05019BA
OE:



FENDER BRACKET
911.CHN01014A
R:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

CHNA

email:market@daiwa-motor.com