

REPLACEMENT FOR


COBALT '12



TAIL LAMP SMOKE
931.CV7113
R:



FRONT BUMPER
901.CV40242BA W/O FOG HOLE
901.CV40243BA W/ FOG HOLE



HEAD LAMP
930.CV7018
R:52020803 L:52020802



MIRROR CABLE
980.CV1130
R:



REAR BUMPER
901.CV40244BA
OE




HEAD LAMP ELECTRIC
930.CV7018E
R:



MIRROR
980.CV1129E
R:



FRONT BUMPER REINFORCEMENT
911.CV44087A
OE:52027637



HEAD LAMP MANUAL SMOKE
930.CV7019
R:



GRILLE
900.CV97157GA
OE



FOG LAMP
939.CV7008
R:



TAIL LAMP
931.CV7112
R:94732092 L:94732091



GRILLE
900.CV97158GA
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only. Our production is not original replacement parts but interchangeable against original parts.

CV

email:market@daiwa-motor.com