

REPLACEMENT FOR

DAMAS 98~



BUMPER LAMP
932.KA9997
OE:



TAIL LAMP
931.KA9148
OE:



HEAD LAMP
930.KA9603
R:35301-60C00 L:35300-60C00



FRONT LAMP CRYSTAL
932P.KA9997
R:35602-70B00-000 L:35601-70B00-000



FRONT BUMPER
901.KA04994BA
OE:



HEAD LAMP CRYSTAL
930P.KA9603
OE:



FRONT LAMP
932.DW9992
OE:



REAR BUMPER
901.KA04995BA
OE:



CORNER LAMP
938.DW7001
OE:



TAIL LAMP
931.DW9147
R:35604-85500 L:35603-85500



LIGHT CASE
913.DW1913
R:72121-83000-000 L:72111-83000-000



SIDE LAMP
932.DW9994
OE:



TAIL LAMP CRYSTAL
931P.DW9147
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

DW

email:market@daiwa-motor.com