

REPLACEMENT FOR

EXPLORER '16~



GRILLE SILVER
900.FD77220GA
OE:FB53-8200-AE1GD3
FB53-8150-ABW



FRONT BUMPER
901.FD05039BA
OE:FB53-17K775-ACW



REAR BUMPER VALENCE
903.FD95033VA
OE:FB53-17K765-ABW



HEAD LAMP
930.FD7296
R:FB53-13005-CK L:FB53-13006-CK



GRILLE BLACK
900.FD77221GA
OE:FB53-8200-AE1GD3
FB53-8150-ABW



FRONT BUMPER LOWER 4WD
901.FD05040BA
OE:FB53-17D997-ACW



FRONT REINFORCMENT
911.FD44176A
OE:



FOG LAMP SMOKE
939.FD7039
R:FB53-15A254-A L:FB53-15A255-A



LOWER GRILLE
900.FD77222GA
OE:FB53-17K945-ACW



REAR BUMPER UPPER
901.FD05041BA
OE:FB53-17D781-AD5G9Z



REAR REINFORCMENT
911.FD44177A
OE:



FOG LAMP
939.FD7038
R:FB53-15A254-C L:FB53-15A255-C



FRONT BUMPER W/SENSOR HOLE
901.FD05037BA W/ TOW COVER
901.FD05037BB W/O TOW COVER
OE:FB53-S17K819-AC5G9Z



REAR BUMPER LOWER
901.FD05042BA
OE:FB53-17F954-AD



FRONT BUMPER BRACKET
911.FD44173A
OE:FB53-12E898-BA



MIRROR ELECTRIC 2.3
980.FD311E
R:GB5Z-17682MC-PTM
L:GB5Z-17683MC-PTM



FRONT BUMPER W/SENSOR& WASHER HOLE
901.FD05038BA W/ TOW COVER
901.FD05038BB W/O TOW COVER



FRONT BUMPER GUARD
903.FD95032VA
OE:FB53-17F771-ABW



FRONT BUMPER BRACKET
911.FD44170A
R:FB53-17E814-A L:FB53-17E814-B

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

FD

email:market@daiwa-motor.com

REPLACEMENT FOR

EXPLORER '16~



INNER FENDER FRONT
915.FD11122
R:FB53-13052-AA L:FB53-13064-AA



AIR CLEANER BOTTOM COVER
241.FD5011
OE:AG1Z9661A



HOOD AIR DUCT
911.FD44174A
OE:FB53-8475-AE



REAR BUMPER BRACKET
911.FD44172A
OE:



INNER FENDER REAR
915.FD11123
R:FB53-7828370-AD
L:FB53-7828371-AD



RADIATOR TANK TOP COVER
911.FD44178A
OE:FB53-8A164-ABW



FENDER TRIM REAR
943.FD12004
R:BB5Z-7829164AA L:BB5Z-7829165AA



REAR BUMPER BRACKET
911.FD44171A
OE:




REAR REFLECTOR
932.FD7014
OE:



RADIATOR AIR DEFLECTOR LH
911.FD44179AL
OE:FB53-8A261-BD



FENDER TRIM FRONT
943.FD12005
R:FB53-16A074-AE L:FB53-16A075-AE



FRONT TOW COVER
911.FD44175A
OE:FB53-17A989-ACW



FOG LAMP COVER W/O HOLE
913.FD7049A
R:FB53-17B968-BDW
L:FB53-17B969-BDW



RADIATOR AIR DEFLECTOR RH
911.FD44179AR
OE:FB53-8A211-BD



MUDGUARD
922.FD6508A
OE:



RADIATOR SUPPORT
904.FD30837A
OE:FB53-105B00-AE



AIR CLEANER TOP COVER
241.FD5010
OE:AA5Z-9A600B



RADIATOR AIR DEFLECTOR UP
911.FD44180A
OE:FB53-811301-D



WINDSHIELD WASHER
509.FD1013A
OE:FB53-7B17B613-AC

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

FD

email:market@daiwa-motor.com