

REPLACEMENT FOR
HOVER



TAIL LAMP UPPER
931.GW3001
R:



FRONT BUMPER
901.GW04001BA
OE:



WINDSHIELD WASHER
509.GW1001A
OE:



HEAD LAMP
930.GW1001
R:



TAIL LAMP LOWER
931.GW3002
R:



REAR BUMPER
901.GW04002BA
OE:




WINDSHIELD WASHER
511.GW1001A
OE:



FOG LAMP
939.GW2001
R:



MIRROR
980.GW001
R:



FRONT BUMPER GRILLE
901G.GW04001BA
OE:



REAR BUMPER LAMP
932.GW2012
R:



GRILLE
900.GW07001GA
OE:



FRONT BUMPER APRON
903.GW05001
OE:



SIDE LAMP
932.GW1001X
R:



GRILLE
900.GW07002GA
OE:



FRONT BUMPER SUPPORT
911.GW44001A
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

GW

email:market@daiwa-motor.com