

REPLACEMENT FOR
SAILOR '04



REAR BUMPER
901.GW04008BA
OE:



HEAD LAMP
930.GW1004
R:



BUMPER GRILLE L/R
901G.GW04008BA
R:



FOG LAMP
939.NS5525
R:



REAR SIDE BUMPER
912.GW41001A
R:



MIRROR
980.GW003
R:



FRONT BUMPER
901.GW04007BA
OE:



REPLACEMENT FOR
SAILOR '07



FRONT BUMPER
901.GW04003BA
OE:



HEAD LAMP
930.GW1023
R:



FRONT BUMPER LOWER
901.GW04004BA
OE:



FOG LAMP
939.GW2022
R:



REAR BUMPER
901.GW04045BA
OE:



TAIL LAMP
931.GW3003
R:



CORNER BUMPER
912.GW41006A
R:



GRILLE
900.GW07003GA
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

GW

email:market@daiwa-motor.com