


REPLACEMENT FOR
WINGLE



SIDE LAMP
932.GW1002X
R:



BUMPER GRILLE L/R
901G.GW04005B
R:




WINDSHIELD WASHER
509.GW1002A
OE:



HEAD LAMP
930.GW1003
R:



TAIL LAMP
931.GW3004
R:



BUMPER GRILLE LOWER
901G.GW04006BA
OE:




FOG LAMP COVER
913.GW0701
R:



HEAD LAMP
930.GW1015
R:



MIRROR
980.GW002
R:



BUMPER GRILLE UP
901G.GW04007BA
OE:



FOG LAMP
939.GW2002
R:



FRONT BUMPER
901.GW04005BA
OE:



MUDGUARD
922.GW15002Z
OE:



REAR BUMPER LAMP
932.GW1003
R:



REAR BUMPER
901.GW04006BA
OE:



SPARE TANK
511.GW1002A
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

GW

email:market@daiwa-motor.com