

REPLACEMENT FOR

# CRV '10



FRONT BUMPER  
901.HD05023BA  
OE: 71101-SWA-ZY00



RADIATOR TANK TOP COVER TBA  
911.HD44131A  
OE: 71141-SWA-000



FOG LAMP TBA  
939.HD2048  
R:33901-SWA-H00 L:33951-SWA-H00



FRONT BUMPER LOWER  
901.HD05024BA  
OE:71102-SWA-ZZ10



REAR BUMPER LAMP  
932.HD7007  
R:





REAR BUMPER  
901.HD05025BA  
OE:71501-SWA-ZZ00



GRILLE  
900.HD08014GB  
OE:71121-SWN-H11



REAR BUMPER LOWER  
901.HD05026BA  
OE:71502-SWA-ZZ00



GRILLE TBA  
900.HD08014GA  
OE:



BUMPER GRILLE  
901G.HD04997BA  
OE:71123-SWN-H11



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.  
Our production is not original replacement parts but interchangeable against original parts.

## HD

email:market@daiwa-motor.com