

REPLACEMENT FOR

**ATOS '01~**



**MIRROR**  
980.HY902  
R:87620-02100 L:87610-20100



**RADIATOR SUPPORT**  
904.HY30220A  
OE: 64101-02000



**AIR FILTER COVER**  
241.HY1026A  
OE: 28110-02000



**HEAD LAMP**  
930.HY1124  
R:92102-06000 L:92101-06000



**FRONT BUMPER**  
901.HY04219BA  
OE:86511-06020



**OUTER HANDLE FRONT**  
882.HY1115F  
OE:



**FOG LAMP**  
939.HY2003  
R:922020-02500 L:922021-02500



**FRONT BUMPER**  
901.HY04218BA  
OE:86511-06000



**FRONT BUMPER REINFORCEMENT**  
911.HY44045A  
OE:86530-06000



**SIDE LAMP**  
932.HY1401  
OE:221-1401




**FRONT BUMPER**  
901.HY04227BA  
OE:



**REAR BUMPER REINFORCEMENT**  
911.HY44046A  
OE:86630-06000



**TAIL LAMP**  
931.HY1906  
R:92402-06000 L:92401-06000



**FRONT BUMPER**  
901.HY04226BA  
OE:



**INNER FENDER**  
915.HY11122  
R:86812-02000 L:86811-02000

All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.  
Our production is not original replacement parts but interchangeable against original parts.

**HY**

email:market@daiwa-motor.com