

REPLACEMENT FOR

EON '14~



MIRROR
980.HY128E
R:87620-4N630 L:87610-4N630



RADIATOR SUPPORT
904.HY30340A
OE:64101-4N010



HEAD LAMP
930.HY7014
R:92102-4N000 L:92101-4N000



FRONT BUMPER
901.HY07027BB
OE:86511-4N010/20



FRONT BUMPER REINFORCEMENT
911.HY44337A
OE:86530-1E000



FOG LAMP
939.HY7211
R:92202-4N000 L:92201-4N000



FRONT BUMPER
901.HY07027BA
OE:86511-4N000



REAR BUMPER REINFORCEMENT
911.HY44338A
OE:86630-1E000




TAIL LAMP
931.HY7101
R:92402-4N000 L:92401-4N000



REAR BUMPER
901.HY07028BA
OE:86611-4N010



FRONT BUMPER GARNISH
923.HY55131A
R:86354-4N000 L:86353-4N000



MIRROR
980.HY127
R:



BUMPER GRILLE
901G.HY04126BA
OE:86561-4N000



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com