


REPLACEMENT FOR

H100 PANEL VAN '93~





MIRROR FRONT BUMPER
980.HY091R
OE:



HEAD LAMP
930.HY3032
R 92102-43420 L 92109-43420



FRONT BUMPER
901.HY04361BA
OE:



CORNER LAMP
938.HY3075
R 9230-43401 L 92201-43401





REAR BUMPER
901.HY04365BA
OE:86611-43300



TAIL LAMP
931.HY1901
R 92402-43300 L 92401-43300



FRONT BUMPER REINFORCEMENT
911.HY44368A
OE:86620-43810



MIRROR
980.HY091L
OE:



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com

REPLACEMENT FOR

H100 PANEL VAN '96~



FOG LAMP
939.HY9135
R:92202-43800 L:92201-43800



FRONT BUMPER
901.HY04362BA
OE:86511-43810



TRUNK LID MOULDING CHROME
923.HY55867A
OE:83910-43360



HEAD LAMP
930.HY1114
R 92102-43810 L 92101-43810



FOG LAMP CRYSTAL
939P.HY9135
R:



FRONT BUMPER
901.HY04362BB
OE:86511-43800



TRUNK LID MOULDING BLACK
923.HY55868A
OE:



HEAD LAMP CRYSTAL
930P.HY1114
R



TAIL LAMP
931.HY1902
R 92402-43810 L 92401-43810



REAR BUMPER
901.HY04360BA
OE:86611-43810



CORNER LAMP
938.HY5587
R 92302-43810 L 92301-43810



TAIL LAMP CRYSTAL
931P.HY1902
R



FRONT REINFORCEMENT TBA
911.HY44369A
OE:86620-43800



CORNER LAMP CRYSTAL
938P.HY5587
R



MIRROR
980.HY013
R 87652-43810 L 87651-43810



FAN SHROUD
512.HY2005A
OE:25390-43010



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com