

REPLACEMENT FOR
i20 '16



BACK LAMP
933.HY7310
R:92404-C7000 L:92403-C7000



REAR BUMPER LOWER
901.HY05013BA
OE:86695-C7000



INNER FENDER
915.HY11123
R:86816-C7000 L:86815-C7000




HEAD LAMP
930.HY7031
R:92102-C7000 L:92101-C7000



TAIL LAMP
931.HY7021
R:92402-C7000 L:92401-C7000



BUMPER GRILLE
901G.HY04048BA
OE:86569-C7000



HEAD LAMP
930.HY7059
R:92102-C8200 L:92101-C8200



GRILLE
900.HY08010GA
OE:86351-C7000



RADIATOR SUPPORT
904.HY30344A
OE:64101-C7000



FOG LAMP
939.HY7232
R:92202-C7000 L:92201-C7000



FRONT BUMPER
901.HY05011BA
OE:86511-C7000



FRONT BUMPER BRACKET
911.HY44373A
R:86516-C7000 L:86515-C7000



REAR BUMPER LAMP
932.HY7011
R:92406-C7000 L:92405-C7000



REAR BUMPER
901.HY05012BA
OE:86611-C7000



REAR BUMPER BRACKET
911.HY44374A
R:86616-C7000 L:86615-C7000



All trademarks and vehicle models (including their names and pictures) mentioned in this catalogue are for reference only.
Our production is not original replacement parts but interchangeable against original parts.

HY

email:market@daiwa-motor.com